



Anna Margaret Barris

Project Designer

Illinois Historic Preservation Agency

Illinois Main Street



Building a Sustainable Future

=

Sustaining Buildings for the Future



Buildings do not always stand up to water



Water damage can be visible



Rust coming
through from
back side

Or relatively obscure




What might have started as a small problem can soon lead to greater problems



Soon materials fall in to total disrepair

Wall is bulging



Water has caused the steel ties to rust. When steel rusts, it expands. Here it is pushing the masonry wall out of plane.




Water can lead to structural problems

If Maintenance issues are not addressed
they will lead to Structural Issues




To protect your building, you must know:



- If your building envelope is sealed.
- What route the water takes.
- Where the water goes.


Your building's envelope includes




- Exterior walls
- Roofs
- Windows
- Storefront
- Any exterior surface



Leaky roof is the best known problem



Check the slope of the roof make sure water does not pool.
Double check flashing around any change in plane.



Flashing should be mortared into the surrounding brick.



Flashing covers the connection of the roof, the side wall and the adjacent brick wall



Flashing covering the connection of the roof and chimney




Inappropriate tar is letting water in.

Water is infiltrating the interior wall.

Mortar loss



Damp mossy interior walls



Probably the most common but unnoticed problem is missing or loose parapet caps (or coping)




Missing parapet cap; water infiltrated wall.

Area was parged over.

Not a solution!



Parapet caps must be mortared in place






Common brick inside wall cavity



Face brick on exterior wall





Common brick inside wall cavity

Face brick on exterior wall




Side walls were constructed with pockets to hold the floor joist



These pockets must be filled with mortar to prevent water from entering the wall



Water can destroy not only this wall but the one on the other side of it as well




When water travels through the wall cavity, it can be stopped by a steel lintel. The lintel will rust, causing rust jacking.



Rust jacking



Rust jacking weakened the mortar joints.



The lintel continues to expand, the caulk seals moisture inside the wall, does nothing to repair the problem



Are you maintaining your original windows?



Original Windows

Fill out this form for you



\$79 PER WINDOW
INSTANT REBATE!
ACT NOW!
Unit of Time Offer Only

Easy,
Tilt-In
Cleaning!

Please complete the f

1. Do you own your home?
2. How old is your home?
3. Years owned?
4. Are your windows orig
5. Why do you want to re

Replacement Windows !

GREAT CURRENT

\$79

SAVINGS

Per Window* NOTHING TO MAIL IN!

INTERNET SPECIAL

SAVE!

Salutation: Mr.

© IHPA 2011

Historic windows were constructed so they could be repaired!





Windows need to be painted to protect the wood



Old brittle putty should be replaced



Broken sash cords should be replaced with
new sash cord...



...or chains



Joints should be tighten



Where there is wood rot or decay, a new member can be installed or wood can be repaired with a consolidant

ADVANCED WOOD REPAIR TECHNOLOGY PROVEN TO SAVE YOUR MAINTENANCE BUDGET

THE PROBLEM

- Open joints
- Decayed wood
- Failed paint
- High maintenance


THE SOLUTION

- Sound joints
- Repaired wood
- Lasting paint
- Low maintenance



Windows: Annual Energy costs

	ANNUAL COST	CONST. COST	PAYBACK
■ Typical wood window	\$ 20	\$ 0	0
■ Add Storm/weatherstrip	\$ 13	\$100	14 yrs
■ New insulated glass	\$ 10	\$400	40 yrs



Add weather stripping to prevent air infiltration



Storm windows interior or exterior












So your building envelope is sealed.

Where does the water go when it is
shed?



Then entering here?

Is water leaving here?

Here moss is growing where the downspout should be connected. Now the building needs cleaned and repointed





Leaky gutters defeat the purpose of downspouts





Leaky gutters defeat the purpose of downspouts





Gutters and Downspouts must be clean, connected and free of leaks!



Now that you know where how the
water is traveling, where is its
destination?





Here the downspout is connected under ground to the storm drainage system.








If water is collecting at the base of the building,



it can creep up in to the brick, a condition called
“rising damp.”




To prevent water from pooling, gravel has been built up against the building.



Parging brick makes the problem worse!



Water is trapped behind the parking, holding moisture against the brick.



Moisture will keep traveling up the wall to escape if it cannot escape through the mortar joints it will force the face off of the historic brick



Coatings such as Modac will trap moisture in wall,
causing more spalling.



The coating has bonded with the hard outer shell of the historic brick.



Bad repointing can damage the brick and change the character of a building





If improper mortar is used spalling will occur



leaving the soft inside of the brick exposed



This can also happen when brick is sandblasted.



Historically, mortar was meant to be the sacrificial layer. It is easier to replace than brick.



When repointing, great care should be taken to not damage the brick.



A low pressure water wash is key when repointing.
The wall should remain wet when repointing.



The new mortar joints should match the old in joint profile, mortar composition, and color.



The new mortar should be mixed by hand on site and tested to match the old mortar in composition, and color.



Packing the new “old” mortar



The joints are then “raked”



and then compressed with a bristle brush



If brick has not been painted then do not paint it, it only introduces an additional maintenance cycle.



If brick has been painted, then the best thing to do is leave it painted and continue the maintenance.



Rusting metals should be painted



Rust can literally erode away the metal.



Lose detail



Damages ornament



Rust looks bad!



To prevent further rusting, steel and iron should be scraped with a wire brush, primed, and painted.



Copper and bronze can be left alone to patina.



When patching, use galvanized metal and screws.
Match the profile.



Wood must be kept painted.

Wood needs protection!







Individual members can be replaced or patched with epoxies.



If wood is exposed it should be protected by paint.

TPS Online Education - Microsoft Internet Explorer

File Edit View Favorites Tools Help


Back Forward Stop Refresh Home Search Favorites

Address http://www.cr.nps.gov/hps/tps/online_ed.htm Go Links >>

Google G Go Bookmarks PageRank 495 blocked Check AutoLink AutoFill Send to Settings

National Park Service

National Park Service
U.S. Department of the Interior



TPS

Technical Preservation Services

ONLINE EDUCATION

For over 25 years, Technical Preservation Services (TPS) has helped home owners, preservation professionals, organizations, and government agencies by publishing printed pamphlets and books--easy-to-read guidance on preserving, rehabilitating and restoring historic buildings. With the increasing popularity of the internet, TPS adapted much of its catalog for electronic access (see the publications page). In addition, TPS has introduced new products, specifically authored for the web, including:

- Home
- Program in Brief
- Publications
- Tax Incentives
- Online Education**
- Standards and Guidelines
- Conferences
- Features
- Heritage Preservation

www.nps.gov/tps/education/online-training.htm

MAIN STREET
WEST VIRGINIA

Downtown

Property

Owners

Maintenance

Manual



Main Street West Virginia Downtown Property Owners Maintenance Manual

Contact: Michael Gioulis

www.michaelgioulis.com

mike@michaelgioulis.com

Any questions?



 Anna Margaret Barris
Project Designer

Illinois Historic Preservation Agency

Illinois Main Street

annamargaret.barris@illinois.gov

217-782-7534



The following are examples of assessments that were completed based on the Site Review Form.

These assessments were done for the local Main Street organization to make sure façade grant funds would address the appropriate repairs.

Technical Assistance
123 N. Dixie (Dixie Barber Shop)



May 25, 2006
Reviewers: Harry Hunderman
& Anna Margaret Borntager

STOREFRONT

● **Windows**

○ Historic, original to storefront.
Glass is cracked in south display window at recessed entrance. Clear acrylic caulk can be used to infill the crack; eventually the glass should be replaced.

○ Steel window frames should be scraped with a wire brush to remove rust and repainted.

Technical Assistance

123 N. Dixie (Dixie Barber Shop)



May 25, 2006

Reviewers: Harry Hunderman
& Anna Margaret Borntager

- Transoms

The original prismatic glass transoms are in very good condition.

- Bulkhead

At recessed entry, historic panels are of steel construction. They should be scraped with a wire brush and repainted. Plywood panels cover the original bulkheads at sidewalk. The plywood panels should be removed, and the original bulkheads (which are probably either steel or glass) should be restored.

- Entrance

Historic door is in good condition. It should be repainted when the storefront is repainted.

Technical Assistance
123 N. Dixie (Dixie Barber Shop)

May 25, 2006

**Reviewers: Harry Hunderman
& Anna Margaret Bortrager**



UPPER FAÇADE

•Windows

Historic windows should be retained and repainted. Consider painting storm windows as well.

•Masonry

Water is infiltrating the parapet brick, most likely at the roof line or at the coping. Roof should be inspected for proper flashing and the coping joints examined.

Spalling is occurring at parapet. The mortar should be removed (by hand) and replaced with Type N or O mortar mixes, taking care not to get mortar on the face of the brick. Mortar should be tinted and joints should be raked to match historic joints.

Technical Assistance

123 N. Dixie (Dixie Barber Shop)



May 25, 2006

Reviewers: Harry Hunderman
& Anna Margaret Bortrager

SIGN

Wooden individual letters no longer represent current business; however are very interesting. The sign can be left in place as is or new letters can be constructed to match the existing. Window graphics are clear and appropriate to the historic character.

STRUCTURAL ISSUES

There are no evident structural issues.

IMMEDIATE RECOMMENDATIONS

Fix water problem at roof/coping
Repoint mortar at area above upper floor windows with correct mortar mix
Remove plywood from bulkheads and restore original material beneath.

Technical Assistance
12 N. Dixie

March 3, 2005
Reviewers: Harry Hunderman
& Darius Bryjka



STOREFRONT

Non historic with the exception of the prism glass transoms, which should be preserved and repaired. Altering the storefront would be costly and is not of high priority. At least, it should be maintained and painted, and a new fabric awning spanning the width of the façade should replace the existing.

Technical Assistance
12 N. Dixie

March 3, 2005
Reviewers: Harry Hunderman
& Darius Bryjka



UPPER FAÇADE

Masonry

Historic Tiffany brick. Any spalling glaze should be flaked off and those areas painted with acrylic paint (Thorosheen).

Windows

Historic. Appear to be in fair condition. Should be repaired and painted.

SIGN

Will be left up to tenant, but should be flush mounted, externally illuminated by gooseneck light fixtures.

**Technical Assistance
12 N. Dixie**

**March 3, 2005
Reviewers: Harry Hunderman
& Darius Bryjka**



STRUCTURAL ISSUES

The steel lintel above the storefront is significantly corroded and the adjacent Tiffany brick is structurally unstable. The face brick is likely debonded from the backup brick. At a minimum, the brick between the prism glass transom and the upper story windows will have to be removed, and the lintel replaced while stabilizing the rest of the masonry above. It may be necessary to install supplementary anchors to secure the Tiffany brick to the backup brick.

**Technical Assistance
12 N. Dixie**

**March 3, 2005
Reviewers: Harry Hunderman
& Darius Bryjka**



IMMEDIATE RECOMMENDATIONS

Replace storefront lintel and secure the Tiffany brick

Repair the transom windows

Repair the upper story windows

Repair areas of spalled brick

Install new awning

Restore the storefront (of low priority)

Technical Assistance
125 N. Dixie

May 25, 2006

**Reviewers: Harry Hunderman
& Anna Margaret Borntager**



STOREFRONT

Windows

Historic bronze or copper-clad window frames in good condition; small corner piece of frame is missing at entrance.

Transoms

Covered with T-111 plywood, this should be removed and the original transoms restored.

Bulkhead

Historic glazed Tiffany brick in great condition.

Entrance

2 historic doors both in good condition. Great terrazzo floor and tin ceiling at recessed entry.

**Technical Assistance
125 N. Dixie**

**May 25, 2006
Reviewers: Harry Hunderman
& Anna Margaret Borntager**



UPPER FAÇADE

•Windows

- Non-historic aluminum windows in wood frames (inappropriate proportions). These should be replaced with new wood windows that fill the entire masonry opening.
- Historic sills should be scraped and cleaned with a nylon bristle brush.
- Steel lintels should be scraped of rust and repainted.

**Technical Assistance
125 N. Dixie**

**May 25, 2006
Reviewers: Harry Hunderman
& Anna Margaret Bortrager**



Masonry

Historic glazed Tiffany brick in fair condition, almost no signs of spalling. It appears that the mortar joints around window lintels have been inappropriately caulked and/or are significantly eroded. Caulking and any loose mortar should be removed and joints should be repointed with Type N or O mortar mix.

SIGN

Current signage is cluttered and ineffective. A new sign should be installed after transom windows are restored. Vinyl window graphics should be used instead of temporary paper signs.

**Technical Assistance
125 N. Dixie**

**May 25, 2006
Reviewers: Harry Hunderman
& Anna Margaret Borntager**



STRUCTURAL ISSUES

There are no evident structural issues.

IMMEDIATE RECOMMENDATIONS

Scrape and paint steel lintels above upper floor windows

Repoint masonry

Remove plywood from transoms and restore the transom windows

Consider replacing the existing upper-floor windows with windows that are historically correct.

