



1. Looking East at West Profile of S.N. 050-0096



2. Looking West at East Profile of S.N. 050-0096



3. Looking East along Vermilion River from S.N. 050-0096 at Sta. 196+85



4. Looking West along Vermilion River from S.N. 050-0096 at Sta. 196+85



5. Looking North along IL 178 through S.N. 050-0096



6. Looking South along IL 178 through S.N. 050-0096



7. Looking North along IL 178 from S.N. 050-0096 at Sta. 196+85



8. Looking South along IL 178 from S.N. 050-0096 at Sta. 196+85



9. Looking North-West at the NW Quad of S.N. 050-0096 from S.N. 050-0096 at Sta. 196+85



10. Looking North-East at the NE Quad of S.N. 050-0096 at Sta. 196+85



11. Looking South-West at the SW Quad of S.N. 050-0096 at Sta. 196+85



12. Looking South-East at the SE Quad of S.N. 050-0096 at Sta. 196+85



13. Looking South-East at Patching on the North Profile of S.N.
50-0096 East Pier #3




14. Looking South-East at Patching on the North Profile of S.N.
50-0096 East Pier #3



15. Looking South-West at Patching on the North Profile of S.N. 050-0096
West Pier #3



16. Looking South-West at Patching along the beams on the North Profile of
S.N. 050-0096 East West Pier #3



17. Looking South-West at Patching on the North Profile of S.N. 050-0096 West Pier #3



18. Looking East at Patching on the West Profile of S.N. 050-0096 West Pier #3



19. Looking East at Patching on the West Profile of S.N. 050-0096 West Pier #3



20. Looking East at Patching on the West Profile of S.N. 050-0096 West Pier #3



21. Looking North-East at Patching underneath S.N. 050-0096 Span #4



22. Looking North-East at Patching underneath S.N. 050-0096 West Span #4



23. Looking North-East at Patching underneath S.N. 050-0096 East Span #4



24. Looking North-East at Patching underneath S.N. 050-0096 West Span #4



25. Looking East at Patching underneath S.N. 050-0096 West Span #4



26. Looking East at Patching underneath S.N. 050-0096 West Span #4



27. Looking East at Patching underneath S.N. 050-0096 West Span #4



28. Looking East at Patching underneath S.N. 050-0096 Span #4



29. Looking North-East at Patching underneath S.N. 050-0096 West Span #4



30. Looking North-East at Patching underneath S.N. 050-0096 West Span #4



31. Looking East at Patching underneath S.N. 050-0096 West Span #4

BLANK



32. Looking East at Patching underneath S.N. 050-0096 West Span #4



33. Looking East at Patching underneath S.N. 050-0096 West Span #4



34. Looking East at Patching underneath S.N. 050-0096 East Span #4



35. Looking East at Patching underneath S.N. 050-0096 East Span #4



36. Looking South-East at Patching underneath S.N. 050-0096 West Span #4



37. Looking South-East at Patching underneath S.N. 050-0096 West Span #4



38. Looking South-East at Patching underneath S.N. 050-0096 West Span #4



39. Looking South at Patching underneath S.N. 050-0096 Span #4



40. Looking South-East at Patching underneath S.N. 050-0096 East Span #4



41. Looking South-West at Patching underneath S.N. 050-0096 East Span #4



42. Looking South-East at Patching underneath S.N. 050-0096 Span #4



43. Looking South at Patching underneath S.N. 050-0096 Span #4



44. Looking South at Patching underneath S.N. 050-0096 West Span #4



45. Looking South at Patching underneath S.N. 050-0096 West Span #4



46. Looking South-West at Patching underneath S.N. 050-0096 West Span #4



47. Looking South at Patching on the North Profile of S.N. 050-0096 Pier #4



48. Looking West at Patching on S.N. 050-0096 Span #4



49. Looking West at Patching on S.N. 050-0096 Span #4



50. Looking West at Patching on the South Profile of S.N. 050-0096 Pier #4



51. Looking South at Patching on the North Profile of S.N. 050-0096 Pier #4



52. Looking South at Patching on the North Profile of S.N. 050-0096 Pier #4



53. Looking South at Patching on the North Profile of S.N. 050-0096 Pier #4



54. Looking West at Patching on S.N. 050-0096 East Span #4



55. Looking West at Patching on S.N. 050-0096 East Span #4



56. Looking West at Patching on S.N. 050-0096 East Span #4



57. Looking West at Patching on S.N. 050-0096 East Span #5



58. Looking West at Patching underneath S.N. 050-0096 East Span #5



59. Looking South-West at Patching underneath S.N. 050-0096 East Span #6



60. Looking South-West at Patching on S.N. 050-0096 Pier #5



61. Looking South at Patching on S.N. 050-0096 Pier #5



62. Looking South-East at Patching on S.N. 050-0096 East Span #5



63. Looking South-East at Patching on S.N. 050-0096 East Span #5



64. Looking South-East at Patching on S.N. 050-0096 West Span #5



65. Looking South-East at Patching on S.N. 050-0096 West Span #5



66. Looking South-East at Patching on S.N. 050-0096 West Span #5



67. Looking South-East at Patching on S.N. 050-0096 West Span #5



68. Looking South-East at West Profile of S.N. 050-0096



69. Looking South-West at S.N. 050-0096 Span #5



70. Looking South-West at East Profile of S.N. 050-0096



71. Looking South-West at East Profile of S.N. 050-0096



72. Looking South at Patching on S.N. 050-0096 underneath East Span #5



73. Looking South at Patching on S.N. 050-0096 underneath East Span #5



74. Looking South at Patching on S.N. 050-0096 underneath East Span #5

BLANK



75. Looking North-West at Patching on S.N. 050-0096 underneath Span #5



76. Looking North at Patching on S.N. 050-0096 West Profile of East Span #5



77. Looking North-East at S.N. 050-0096 West Span #5



78. Looking North-East at S.N. 050-0096 West Profile of Pier #5




79. Looking North at Patching on S.N. 050-0096 underneath Span #5



80. Looking North at Patching on S.N. 050-0096 South Profile of Pier #4



81. Looking West at Patching on S.N. 050-0096 Pier #5



82. Looking West at Patching on S.N. 050-0096 Pier #5



83. Looking North at Patching on S.N. 050-0096 South Profile of Pier #4



84. Looking North at Patching on S.N. 050-0096 South Profile of Pier #5



85. Looking East at Patching on S.N. 050-0096 underneath Span #6



86. Looking North at Patching on S.N. 050-0096 underneath Span #6



87. Looking North-East at Patching on S.N. 050-0096 South Profile of Pier #5



88. Looking North at Patching on S.N. 050-0096 underneath East Span #6



89. Looking North at Patching on S.N. 050-0096 underneath Span #6



90. Looking North-East at Patching on S.N. 050-0096 South Profile of Pier #5



91. Looking North-East at Patching on S.N. 050-0096 West Profile of Pier #5



92. Looking North-East at Patching on S.N. 050-0096 West Span #5



93. Looking East at Patching on S.N. 050-0096 underneath East Span #6



94. Looking North at Patching on S.N. 050-0096 underneath West Span #6



95. Looking East at Patching on S.N. 050-0096 South Profile of Pier #5



96. Looking East at Patching on S.N. 050-0096 underneath Span #6



97. Looking North-East at Patching on S.N. 050-0096 underneath Span #6



98. Looking North-East at Patching on S.N. 050-0096 underneath Span #5



99. Looking North-East at Patching on S.N. 050-0096 East Span #6



100. Looking North at Patching on S.N. 050-0096 underneath East Span #6



101. Looking North at Patching on S.N. 050-006 underneath Span #6



102. Looking West at Patching on S.N. 050-0096 underneath Span #6



103. Looking South at Patching on S.N. 050-0096 North Profile of Pier #6



104. Looking South-East at Patching on S.N. 050-0096 North Profile of Pier #6



105. Looking South-West at Patching on S.N. 050-0096 North Profile of Pier #6



106. Looking South at Patching on S.N. 050-0096 North Profile of Pier #6



107. Looking East at Patching on S.N. 050-0096 inside East Pier #6



108. Looking East at Patching on S.N. 050-0096 inside East Pier #6



109. Looking East at Patching on S.N. 050-0096 inside East Pier #6



110. Looking East at Patching on S.N. 050-06 inside East Pier #6



111. Looking East at Patching on S.N. 050-0096 inside East Pier #6



112. Looking West at Patching on S.N. 050-0096 inside West Pier #6



113. Looking North at Patching on S.N. 050-0096 South Profile of Pier #6



114. Looking North at Patching on S.N. 050-0096 South Profile of Pier #6



115. Looking North at Patching on S.N. 050-0096 South Profile of Pier #6

BLANK



116. Looking North at Patching on S.N. 050-0096 South Profile of Pier #6

BLANK



117. Looking South-West at S.N. 050-0096 East Profile of Span #6



118. Looking South-East at S.N. 050-0096 West Profile of Span #6



119. Looking South-West at S.N. 050-0096 East Profile



120. Looking South-West at S.N. 050-0096 East Profile



121. Looking North-West at S.N. 050-0096 East Profile of Span #5



122. Looking North-East at S.N. 050-0096 West Profile of Span #4



123. Looking West at S.N. 050-0096 East Profile of Span #6



124. Looking South-East at S.N. 050-0096 West Profile



125. Looking North-West at S.N. 050-0096 East Profile of Span #4



126. Looking East at S.N. 050-0096 West Profile of Span #6



127. Looking North-West at S.N. 050-0096 East Profile of Span #4



128. Looking North at S.N. 050-0096 West Profile



129. Looking North-East at Patching underneath S.N. 050-0096 Span #4



130. Looking North-West at S.N. 050-0096 East Profile of Pier #3



131. Looking North-East at S.N. 050-0096 West Profile of Pier #3



132. Looking North-West at S.N. 050-0096 East Profile of Pier #4



133. Looking North-East at S.N. 050-0096 West Profile of Pier #4



134. Looking East at S.N. 050-0096 West Profile of Pier #5



135. Looking East at S.N. 050-0096 West Profile of Pier #5



136. Looking West at S.N. 050-0096 East Profile of Pier #5



137. Looking West at Patching on S.N. 050-0096 South Profile of Pier #6



138. Looking North-East at Patching on S.N. 050-0096 South Profile of Pier #6



139. Looking North-West at Patching on S.N. 050-0096 South Profile of Pier #6



140. Looking North at Patching on S.N. 050-0096 South Profile of Pier #6



141. Looking North at Patching on S.N. 050-0096 South Profile of Pier #5



142. Looking North at Patching underneath S.N. 050-0096 Span #6



143. Looking North-East at Patching on S.N. 050-0096 South Profile of Pier #5



144. Looking North-West at Patching underneath S.N. 050-0096 Span #5



145. Looking North-East at Patching on S.N. 050-0096 South Profile of Pier #4



146. Looking North-West at Patching underneath S.N. 050-0096 Span #5



147. Looking North at Patching underneath S.N. 050-0096 West Span #5



148. Looking North at Patching underneath S.N. 050-0096 East Span #5



149. Looking North at Patching on S.N. 050-0096 South Profile of Pier #4



150. Looking North-West at Patching on S.N. 050-0096 South Profile of Pier #4



151. Looking North-West at Patching on S.N. 050-0096 South Profile of Pier #5



152. Looking North-West at Patching on S.N. 050-0096 South Profile of Pier #4



153. Looking North-West at Patching on S.N. 050-0096 Pier #4




154. Looking North-West at Patching on S.N. 050-0096 East Profile of East Span #5



155. Looking North-West at Patching on S.N. 050-0096 East Profile of East Span #5



156. Looking North-West at Patching on S.N. 050-0096 East Profile of East Span #5



157. Looking North-West at Patching on S.N. 050-0096 East Profile of East Span #5



158. Looking North-West at Patching on S.N. 050-0096 East Profile of East Span #5



159. Looking North-West at Patching on S.N. 050-0096 East Profile of East Span #5



160. Looking North-West at Patching on the East Profile of S.N. 050-0095 West Span #6



161. Looking North-West at Patching on the East Profile of S.N. 050-0096
West Span #6



162. Looking North-West at Patching on the East Profile of S.N. 050-0096
West Span #6



163. Looking North-West at Patching on S.N. 050-0096 East Profile of Pier
#5



164. Looking North-West at Patching on S.N. 050-0096 East Profile of Pier
#5



165. Looking North-West at Patching on S.N. 050-0096 East Profile of Pier #5



166. Looking North-East at Patching on S.N. 050-0096 West Profile of Pier #5



167. Looking North-East at Patching on S.N. 050-0096 West Profile of Pier #5



168. Looking North-East at Patching on S.N. 050-0096 inside Pier #5



169. Looking North-West at Patching on S.N. 050-0096 West Profile of Pier #5



170. Looking North-East at Patching on S.N. 050-0096 South Profile of Pier #4



171. Looking North-East at Patching on S.N. 050-0096 West Profile of West Span #5



172. Looking North-East at Patching on S.N. 050-0096 West Profile of West Span #5



173. Looking North-East at Patching underneath S.N. 050-0096 East Span #5



174. Looking North-East at Patching underneath S.N. 050-0096 Span #5



175. Looking North at Patching underneath S.N. 050-0096 East Span #6



176. Looking North at Patching underneath S.N. 050-0096 East Span #6



177. Looking North at Patching underneath S.N. 050-0096 Span #6



178. Looking North at Patching underneath S.N. 050-0096 Span #6



179. Looking North at Patching underneath S.N. 050-0096 Span #6



180. Looking South at Patching on the inside of S.N. 050-0096 Pier #6



181. Looking directly up at patching underneath S.N. 050-0096 East Span #6



182. Looking directly up at patching underneath S.N. 050-0096 East Span #6



183. Looking directly up at Patching underneath S.N. 050-0096 Span #6



184. Looking East at Patching on S.N. 050-0096 West Profile of West Span #6



185. Looking North at Patching underneath S.N. 050-0096 East Span #6



186. Looking North at Patching underneath S.N. 050-0096 Span #6



187. Looking North at Patching underneath S.N. 050-0096 West Span #6



188. Looking West at Patching underneath S.N. 050-0096 West Span #6