







1. Looking East at Patching on the West Profile of S.N. 050-0096



2. Looking East at Patching on the West Profile of S.N. 050-0096



3. Looking South at Patching on the West Profile of S.N. 050-0096



4. Looking East at Patching on the West Profile of S.N. 050-0096



5. Looking South-West at Patching on the East Profile of S.N. 050-0096



6. Looking West at Patching on the East Profile of S.N. 050-0096



7. Looking South at Patching on the East Profile of S.N. 050-0096



8. Looking North-West at Patching on the East Profile of S.N. 050-0096



9. Looking North-East at Patching on the West Profile of S.N. 050-0096



10. Looking South along IL 178 through S.N. 050-0096 at Sta. 196+85



11. Looking East at Patching on the West Profile of S.N. 050-0096



12. Looking South at Patching on the West Profile of S.N. 050-0096



13. Looking South-West at Patching on the North Profile of S.N. 050-0096 West Pier #3



14. Looking South-West at Patching on the North Profile of S.N. 050-0096 West Pier #3



15. Looking South-West at Patching on the North Profile of S.N. 050-0096 West Pier #3



16. Looking South at Patching on the North Profile of S.N. 050-0096 West Pier #3



17. Looking South-East at Patching on the North Profile of S.N.
50-0096 East Pier #3



18. Looking South-East at Patching on the North Profile of S.N.
50-0096 East Pier #3



19. Looking South-East at Patching on the North Profile of S.N.
50-0096 East Pier #3



20. Looking South-East at Patching on the North Profile of S.N.
50-0096 East Pier #3



21. Looking East at Patching on the West Profile of S.N. 050-0096 West Pier #3



22. Looking East at Patching on the West Profile of S.N. 050-0096 West Pier #3



23. Looking East at Patching on the West Profile of S.N. 050-0096 West Pier #3



24. Looking East at Patching on the West Profile of S.N. 050-0096 West Pier #3



25. Looking East at Patching on the West Profile of S.N. 050-0096 West Pier #3



26. Looking North at Patching on the South Profile of S.N. 050-0096 West Pier #3



27. Looking East at Patching underneath S.N. 050-0096 Span #4



28. Looking North-East at Patching underneath S.N. 050-0096 Span #4



29. Looking East at Patching on the South Profile of S.N. 050-0096 West Pier #3



30. Looking North at Patching on the South Profile of S.N. 050-0096 West Pier #3



31. Looking North-East at Patching on the South Profile of S.N. 050-0096 West Pier #3



32. Looking East at Patching on the South Profile of S.N. 050-0096 West Pier #3



33. Looking North at Patching underneath S.N. 050-0096 East Span #4



34. Looking North-East at Patching underneath S.N. 050-0096 East Span #4



35. Looking West at Patching underneath S.N. 050-0096 West Span #4



36. Looking West at Patching underneath S.N. 050-0096 East Span #4



37. Looking North-East at Patching underneath S.N. 050-0096 West Span #4



38. Looking South at Patching underneath S.N. 050-0096 West Span #4



39. Looking South at Patching underneath S.N. 050-0096 Span #4



40. Looking South at Patching underneath S.N. 050-0096 West Span #4



41. Looking South-West at Patching underneath S.N. 050-0096 West Span #4




42. Looking South-East at Patching underneath S.N. 050-0096 West Span #4



43. Looking South at Patching underneath S.N. 050-0096 East Span #4



44. Looking South at Patching underneath S.N. 050-0096 Span #4



45. Looking South at Patching underneath S.N. 050-0096 West Span #4



46. Looking South at Patching underneath S.N. 050-0096 West Span #4



47. Looking South-East at Patching underneath S.N. 050-0096 East Span #4



48. Looking South-East at Patching underneath S.N. 050-0096 Span #4



49. Looking North at Patching underneath S.N. 050-0096 West Span #4



50. Looking South at Patching underneath S.N. 050-0096 West Span #4



51. Looking East at Patching underneath S.N. 050-0096 West Span #4



52. Looking East at Patching underneath S.N. 050-0096 West Span #4



53. Looking East at Patching underneath S.N. 050-0096 West Span #4



54. Looking South at Patching underneath S.N. 050-0096 Span #4



55. Looking South-East at Patching underneath S.N. 050-0096 West Span #4



56. Looking South-East at Patching underneath S.N. 050-0096 Span #4




57. Looking East at Patching underneath S.N. 050-0096 East Span #4



58. Looking East at Patching underneath S.N. 050-0096 East Span #4



59. Looking South at Patching underneath S.N. 050-0096 West Span #4



60. Looking South at Patching underneath S.N. 050-0096 East Span #4



61. Looking Directly Up at Patching underneath S.N. 050-0096 West Span #4



62. Looking East at Patching underneath S.N. 050-0096 West Span #4



63. Looking South at Patching underneath S.N. 050-0096 West Span #4



64. Looking South at Patching underneath S.N. 050-0096 West Span #4



65. Looking East at Patching on S.N. 050-0096 Span #4



66. Looking East at Patching underneath S.N. 050-0096 East Span #4



67. Looking West at Patching on S.N. 050-0096 Span #4



68. Looking South at Patching underneath S.N. 050-0096 Span #4



69. Looking South at Patching underneath S.N. 050-0096 West Span #4



70. Looking South-East at Patching underneath S.N. 050-0096 East Span #4



71. Looking South at Patching underneath S.N. 050-0096 Span #4



72. Looking South at Patching on the North Profile of S.N. 050-0096 Pier #4



73. Looking South at Patching underneath S.N. 050-0096 East Span #4



74. Looking South at Patching underneath S.N. 050-0096 West Span #4



75. Looking North-West at Patching on & under S.N. 050-0096 Span #4



76. Looking North-East at Patching on & under S.N. 050-0096 Span #4



77. Looking South-East at Patching on the North Profile of S.N. 050-0096
Pier #4



78. Looking South-West at Patching on the North Profile of S.N. 050-0096
Pier #4



79. Looking South-West at Patching on the North Profile of S.N. 050-0096
Pier #4



80. Looking South-East at Patching on the West Profile of S.N. 050-0096
Pier #4



81. Looking South at Patching on the North Profile of S.N. 050-0096 Pier #4



82. Looking South-East at Patching on the West Profile of S.N. 050-0096 Pier #4



83. Looking South-East at Patching on the West Profile of S.N. 050-0096 Pier #4



84. Looking North-East at Patching on the South Profile of S.N. 050-0096 Pier #4



85. Looking South-West at Patching on the East Profile of S.N. 050-0096 Pier #4



86. Looking West at Patching on the East Profile of S.N. 050-0096 Pier #4



87. Looking North at Patching on the West Profile of S.N. 050-0096 Pier #4



88. Looking South at the East Profile of S.N. 050-0096 Pier #4



89. Looking South-West at Patching on the North Profile of S.N. 050-0096 Pier #4



90. Looking North-East at Patching on the South Profile of S.N. 050-0096 Pier #4



91. Looking North at Patching on the South Profile of S.N. 050-0096 Pier #4



92. Looking North at Patching on the West Profile of S.N. 050-0096 Pier #4



93. Looking North-East at Patching on the South Profile of S.N. 050-0096 Pier #4



94. Looking North-East at Patching on the South Profile of S.N. 050-0096 Pier #4



95. Looking North at the East Profile of S.N. 050-0096 Pier #4



96. Looking North-West at Patching on the South Profile of S.N. 050-0096 Pier #4



97. Looking North-East at Patching on the West Profile of S.N. 050-0096
Span #5



98. Looking North-East at Patching on the West Profile of S.N. 050-0096
Span #5



99. Looking South-East at Patching on the West Profile of S.N. 050-0096
Span #5



100. Looking North-East at Patching on the West Profile of S.N. 050-0096
Span #5



101. Looking South at Patching underneath S.N. 050-0096 East Span #5



102. Looking South-West at Patching underneath S.N. 050-0096 West Span #5



103. Looking South-East at Patching on the West profile of S.N. 050-0096 Span #5



104. Looking South-East at Patching underneath S.N. 050-0096 Span #5



105. Looking South-East at Patching underneath S.N. 050-0096 East Span #5



106. Looking South at Patching underneath S.N. 050-0096 East Span #5



107. Looking South at Patching underneath S.N. 050-0096 East Span #5



108. Looking South at Patching underneath S.N. 050-0096 East Span #5



109. Looking South at Patching on the West Profile of S.N. 050-0096 West Span #5



110. Looking South-East at Patching on the West Profile of S.N. 050-0096 West Span #5



111. Looking North-East at Patching on the West Profile of S.N. 050-0096 West Span #5



112. Looking North-East at Patching on the West Profile of S.N. 050-0096 West Span #5



113. Looking South-East at Patching underneath S.N. 050-0096 East Span #5



114. Looking South-East at Patching underneath S.N. 050-0096 East Span #5



115. Looking North-East at Patching on the West Profile of S.N. 050-0096 West Span #5



116. Looking South-East at Patching on the West Profile of S.N. 050-0096 West Span #5



117. Looking South-East at Patching underneath S.N. 050-0096 Span #5



118. Looking South-East at Patching on the West Profile of S.N. 050-0096 West Span #5



119. Looking South-East at Patching on the West Profile of S.N. 050-0096 West Span #5



120. Looking South-East at Patching on the West Profile of S.N. 050-0096 West Span #5



121. Looking North-East at Patching underneath S.N. 050-0096 Span #5



122. Looking East at Patching on the West Profile of S.N. 050-0096 Span #5



123. Looking North at Patching underneath S.N. 050-0096 West Span #5



124. Looking North-West at Patching underneath S.N. 050-0096 Span #5



125. Looking South at Patching underneath S.N. 050-0096 East Span #5



126. Looking North-West at Patching on S.N. 050-0096 East Span #5



127. Looking South-West at Patching on the North Profile of S.N. 050-0096 Pier #5



128. Looking South-East at Patching on the North Profile of S.N. 050-0096 Pier #5



129. Looking South at Patching on the North Profile of S.N. 050-0096 Pier #5



130. Looking South at Patching on the North Profile of S.N. 050-0096 Pier #5



131. Looking North at Patching on the South Profile of S.N. 050-0096 Pier #5



132. Looking South at Patching on the West Profile of S.N. 050-0096 Pier #5



133. Looking South-West at Patching on the East Profile of S.N.
050-0096 Pier #5



134. Looking South-West at Patching on the East Profile of S.N.
050-0096 Pier #5



135. Looking North at Patching on the West Profile of S.N. 050-0096 Pier #5



136. Looking North-West at Patching on the South Profile of S.N.
050-0096 Pier #5



137. Looking North at Patching on the South Profile of S.N. 050-0096 Pier #5



138. Looking North-West at Patching on the East Profile of S.N. 050-0096 Pier #5



139. Looking North at Patching on the South Profile of S.N. 050-0096 Pier #5



140. Looking North-West at Patching on the East Profile of S.N. 050-0096 Pier #5



141. Looking West at Patching on the South Profile of S.N. 050-0096 Pier #5



142. Looking North-East at Patching on the West Profile of S.N. 050-0096 Pier #5



143. Looking North at Patching on the South Profile of S.N. 050-0096 Pier #5



144. Looking East at Patching on the West Profile of S.N. 050-0096 Pier #5



145. Looking East at Patching on the West Profile of S.N. 050-0096 Pier #5



146. Looking East at Patching on the West Profile of S.N. 050-0096 Pier #5



147. Looking East at Patching on the West Profile of S.N. 050-0096 Pier #5



148. Looking South at Patching on the West Profile of S.N. 050-0096 Pier #5



149. Looking North at Patching on the South Profile of S.N. 050-0096 Pier #5



150. Looking North at Patching on the South Profile of S.N. 050-0096 Pier #5



151. Looking East at Patching on the West Profile of S.N. 050-0096 Pier #5



152. Looking South-East at Patching on the North Profile of S.N. 050-0096 Pier #5



153. Looking South-East at Patching on the North Profile of S.N.
050-0096 Pier #5



154. Looking South-East at Patching on the West Profile of S.N.
050-0096 Pier #5



155. Looking South-East at Patching on the West Profile of S.N.
050-0096 Pier #5



156. Looking South-East at Patching on the North Profile of S.N.
050-0096 Pier #5



157. Looking South-East at Patching on the North Profile of S.N. 050-0096 Pier #5



158. Looking South-East at Patching on the North Profile of S.N. 050-0096 Pier #5



159. Looking North at Patching on the West Profile of S.N. 050-0096 Pier #5



160. Looking North at Patching on the South Profile of S.N. 050-0096 Pier #5



161. Looking North at Patching underneath S.N. 050-0096 East Span #5



162. Looking North-West at Patching on the South Profile of S.N. 050-0096 Pier #5



163. Looking South-East at Patching on the West Profile of S.N. 050-0096 Pier #5



164. Looking North-West at Patching on the South Profile of S.N. 050-0096 Pier #5



165. Looking North-East at Patching on the South Profile of S.N. 050-0096 Pier #5



166. Looking East at Patching underneath S.N. 050-0096 Span #6



167. Looking North-East at Patching underneath S.N. 050-0096 Span #5



168. Looking South at Patching on the West Profile of S.N. 050-0096 West Span #6



169. Looking North at Patching underneath S.N. 050-0096 Span #6



170. Looking West at Patching on the East Profile of S.N. 050-0096 Span #6



171. Looking South-East at Patching on the West Profile of S.N. 050-0096 West Span #6



172. Looking North at Patching underneath S.N. 050-0096 Span #6



173. Looking South-East at Patching on the West Profile of S.N. 050-0096 West Span #6



174. Looking South-East at Patching on the West Profile of S.N. 050-0096 West Span #6



175. Looking East at Patching on the West Profile of S.N. 050-0096 West Span #6



176. Looking South-East at Patching on the West Profile of S.N. 050-0096 West Span #6



177. Looking East at Patching on the West Profile of S.N. 050-0096 West Span #6



178. Looking South-East at Patching on the West Profile of S.N. 050-0096 West Span #6



179. Looking South-East at Patching on the West Profile of S.N. 050-0096 West Span #6



180. Looking Directly Up at Patching on S.N. 050-0096 East Span #6



181. Looking Directly Up at Patching underneath S.N. 050-0096 East Span #6



182. Looking Directly Up at Patching underneath S.N. 050-0096 East Span #6



183. Looking South-West at Patching underneath S.N. 050-0096 East Span #6



184. Looking South-East at Patching underneath S.N. 050-0096 East Span #6



185. Looking Directly Up at Patching underneath S.N. 050-0096 West Span #6



186. Looking Directly up at Patching underneath S.N. 050-0096 East Span #6



187. Looking Directly Up at Patching underneath S.N. 050-0096 East Span #6



188. Looking North-East at Patching on the inside of S.N. 050-0096 Pier #6



189. Looking North at Patching underneath S.N. 050-0096 West Span #6



190. Looking North-West at Patching on the East Profile of S.N. 050-0096 West Span #6




191. Looking Directly Up at Patching underneath S.N. 050-0096 West Span #6



192. Looking North at Patching underneath S.N. 050-0096 East Span #6




193. Looking North-West at Patching underneath S.N. 050-0096 West Span #6



194. Looking Directly Up at Patching underneath S.N. 050-0096 West Span #6



195. Looking North at Patching on the South Profile of S.N. 050-0096 Pier #5



196. Looking North at Patching underneath S.N. 050-0096 East Span #6



197. Looking Directly Up at Patching underneath S.N. 050-0096 West Span #6



198. Looking Directly Up at Patching underneath S.N. 050-0096 West Span #6



199. Looking North-West at Patching on the West Profile of S.N. 050-0096 East Span #6



200. Looking East at Patching underneath S.N. 050-0096 East Span #6



201. Looking North at patching underneath S.N. 050-0096 East Span #6



202. Looking North-East at Patching on the inside of S.N. 050-0096 Pier #6



203. Looking South at Patching on the North Profile of S.N. 050-0096 Pier #6



204. Looking South-East at Patching on the North Profile of S.N. 050-0096 Pier #6



205. Looking East at Patching on the inside of S.N. 050-0096 Pier #6



206. Looking East at Patching on the inside of S.N. 050-0096 Pier #6



207. Looking East at Patching on the inside of S.N. 050-0096 Pier #6



208. Looking East at Patching on the inside of S.N. 050-0096 Pier #6



209. Looking North at Patching on the South Profile of S.N. 050-0096 Pier #6



210. Looking North at Patching on the South Profile of S.N. 050-0096 Pier #6



211. Looking East at Patching on the South Profile of S.N. 050-0096 Pier #6



212. Looking South at Patching on the North Profile of S.N. 050-0096 Pier #6



213. Looking South at Patching on the North Profile of S.N. 050-0096 Pier #6



214. Looking North at Patching on the South Profile of S.N. 050-0096 West Pier #7