



IN REPLY REFER TO:

United States Department of the Interior

NATIONAL PARK SERVICE

Lincoln Home National Historic Site
413 South Eighth Street
Springfield, Illinois 62701-1905

February 10, 2023

Ms. Carol "CJ" Wallace
Cultural Resources Coordinator
Illinois Department of Natural Resources
Attn: State Historic Preservation Office
One Natural Resources Way
Springfield, IL 62702

Re: Annual Report on Use of Streamlined Review for Section 106 Compliance by Lincoln Home National Historic Site

Dear Ms. Wallace:

The Programmatic Agreement (PA) for Section 106 Compliance signed by the National Council of Preservation Officers, the Advisory Council on Historic Preservation, and the National Park Service in 2008 contains a number of reporting requirements. Among these is an annual report to the SHPOs listing all undertakings reviewed using the Streamlined Review process (See Section III.B.5 (d) in the PA for this reporting requirement).

Enclosed please find an Excel report fulfilling the annual requirement. It contains a list of all undertakings at Lincoln Home National Historic Site that used the streamlined review process along with the cultural resource management specialists who reviewed the undertakings.

The Cultural Resource Management Team (CRM Team) reviewing the compliance requests for 2022 were:

- Archeologist
 - Jacob Moody, Midwest Archeological Center
 - Tim Schilling, Midwest Archeological Center
- Chief of Maintenance
 - Jason Taylor, Lincoln Home National Historic Site
- Curator
 - Susan M. Haake, Lincoln Home National Historic Site
 - Heather Young, Midwest Regional Office
- Historians
 - Timothy Townsend, Lincoln Home National Historic Site
 - Ron Cockrel, Midwest Regional Office

- Historical Architect
 - William Harlow, Midwest Regional Office
- Historical Landscape Architect
 - Marla McEnaney, Midwest Regional Office
- Museum Program Manager
 - Keely Rennie-Tucker, Midwest Regional Office
- National Historic Register Coordinator
 - David Calease, Midwest Regional Office
 - Tim Schilling, Midwest Regional Office
- Park Section 106 Coordinator
 - Susan M. Haake, Lincoln Home National Historic Site
- Regional 106 Reviewer
 - Suika Rivett, Midwest Regional Office

We will retain a copy of these reports and provide further copies to the SHPO should the SHPO request these. Please do not hesitate to contact me if you have any questions or comments about our use of the PA.

If you have any questions about any of the above, please do not hesitate to contact me at (217) 391-3222 or timothy_good@nps.gov.

Sincerely,



Timothy Good
Superintendent

Enclosure

Cc: MWRO 106 Advisor

Report - NHPA Annual/Biennial Report 02/10/2023

Report Criteria

Region: All

Park: Lincoln Home NHS

Project ID:

Doc Method: Streamlined Review (PA)

Superintendent Aç 2022

Superintendent Aç 2022

NHPA Annual/Biennial Report Results (found total '15')

Park	PEPC ID	Project Title	Superintendent Approval Date	Assessment of Effect	Documentation Method	Streamline Review Activity	SHPO Consult Required	THPO Consult Required	Additional Consulting Parties	Historical Landscape Architect	Historical Architect	Archeologist	Historian	Anthropologist	Curator	Other Advisor	106 Advisor	State
LIHO	77013	Repair and Paint Exterior of Lincoln Home	1/12/2022	No Adverse Effect	Streamlined Review (PA)	1 - Preservation Maintenance and Repair of Historic Properties	No		No	No	Yes	Yes	Yes	No	Yes	Yes	No	IL
LIHO	77698	Replace Gate Arm Units on East & West Alleys to Improve Visitor Safety/Accessibility	1/12/2022	No Adverse Effect	Streamlined Review (PA)	4 - Health and Safety Activities,9 - Maintenance or Replacement of Non-Historic Utility Lines, Transmission Lines, and Fences,14 - Mechanical, Electrical and Plumbing Systems	No		No	Yes	No	Yes	Yes	No	Yes	Yes	No	IL
LIHO	106008	Repair and Paint Exterior of Shutt House (HS-17)	1/12/2022	No Adverse Effect	Streamlined Review (PA)	1 - Preservation Maintenance and Repair of Historic Properties	No		No	No	Yes	No	Yes	No	Yes	Yes	No	IL
LIHO	99088	Replace Main Components of Fire Suppression System at Lincoln Home (HS-01)	1/12/2022	No Adverse Effect	Streamlined Review (PA)	1 - Preservation Maintenance and Repair of Historic Properties,4 - Health and Safety Activities,14 - Mechanical, Electrical and Plumbing Systems	No		No	No	Yes	No	Yes	No	Yes	Yes	No	IL
LIHO	92446	Fee-FEPR- Replace Landscaping Around North Side of Visitor Center to Increase Visitor Satisfaction	1/12/2022	No Historic Proper	Streamlined Review (PA)	5 - Routine Grounds Maintenance	No		No	Yes	No	No	Yes	No	Yes	No	No	IL
LIHO	77688	Replace Carpet Tiles in VC Theaters 1 and 2 to Enhance Visitor Satisfaction	1/12/2022	No Historic Proper	Streamlined Review (PA)	4 - Health and Safety Activities	No		No	No	Yes	No	Yes	No	Yes	Yes	No	IL
LIHO	106349	Repair crack/hole in Lincoln Home (HS-01) foundation causing leak into basement	1/19/2022	No Adverse Effect	Streamlined Review (PA)	1 - Preservation Maintenance and Repair of Historic Properties	No		No	Yes	Yes	Yes	Yes	No	Yes	Yes	No	IL
LIHO	77682	Replace Copper Metal Roofs on Lyon/Rosenwald (HS-08), Beedle (HS-12), and Dean (HS-13) Houses	1/26/2022	No Adverse Effect	Streamlined Review (PA)	1 - Preservation Maintenance and Repair of Historic Properties	No		No	No	Yes	No	Yes	No	Yes	Yes	No	IL
LIHO	106726	Replace wooden boardwalks with standard broom-finish concrete at the rear of 8 houses in Lincoln neighborhood	1/27/2022	No Adverse Effect	Streamlined Review (PA)	2 - Rehabilitation and/or Minor Relocation of Existing Trails, Walks, Paths, and Sidewalks,4 - Health and Safety Activities	No		No	Yes	No	Yes	Yes	No	Yes	No	No	IL
LIHO	109789	Remove damaged Crabapple trees near Lincoln Barn (HS-01A) and Arnold Barn (S-25) and replace with Dogwoods	6/2/2022	No Adverse Effect	Streamlined Review (PA)	5 - Routine Grounds Maintenance	No		No	Yes	Yes	Yes	Yes	No	Yes	Yes	No	IL
LIHO	106791	Replace Fire Suppression System at Cook House	6/24/2022	No Adverse Effect	Streamlined Review (PA)	14 - Mechanical, Electrical and Plumbing Systems	No		No	No	Yes	No	Yes	No	Yes	Yes	Yes	IL
LIHO	110853	Remove dying Chinese Elm tree and replace in-kind in backyard of Robinson House (HS-10)	7/15/2022	No Adverse Effect	Streamlined Review (PA)	4 - Health and Safety Activities,5 - Routine Grounds Maintenance	No		No	Yes	No	Yes	Yes	No	Yes	Yes	No	IL
LIHO	111989	Insert Lightning Rods around Perimeter of Grace Lutheran Church (in holding)	9/26/2022	No Adverse Effect	Streamlined Review (PA)	1 - Preservation Maintenance and Repair of Historic Properties,14 - Mechanical, Electrical and Plumbing Systems	No		No	Yes	Yes	Yes	No	No	Yes	Yes	No	IL
LIHO	77019	Replace Roof on Corneau Barn and Privy	12/19/2022	No Adverse Effect	Streamlined Review (PA)	1 - Preservation Maintenance and Repair of Historic Properties	No		No	Yes	Yes	No	Yes	No	Yes	Yes	No	IL
LIHO	77687	Replace Carpet Tiles in VC Lobby to Enhance Visitor Satisfaction	12/19/2022	No Historic Proper	Streamlined Review (PA)	2 - Rehabilitation and/or Minor Relocation of Existing Trails, Walks, Paths, and Sidewalks	No		No	No	No	No	No	No	Yes	Yes	No	IL